| PRODUCT NUMBER | LENGTH | TOLERANCE | WIRING DIAGRAM "A" | WIRING DIAGRAM "B" |
|---|---|---|---|---|
| 10070044-001LF | .5 METER | ±0.03 METER | X | |
| 10070044-002LF | 10 METER | ±0.05 METER | X | |
| 10070044-003LF | .5 METER | ±0.03 METER | | X |
| 10070044-004LF | 10 METER | ±0.05 METER | | X |
| 10070044-005LF | .6 METER | ±0.03 METER | X | X |
| 10070044-006LF | .6 METER | ±0.03 METER | | X |




NOTES:

1. ELECTRICAL TEST: CONTINUITY,HI POT TEST, RESISTANCE NO LESS THAN 2Mohms,10mS.
2. PART NUMBERS WITH "LF" SUFFIX AT THE END ARE LEAD FREE OPTION.
3. PACKAGE PER GS-14-920 FOR LEAD FREE PACKAGING REQUIREMENTS.

WIRING DIAGRAM

| A | | B | |
|---|---|---|---|
| GND | A1 | GND | A1 |
| GND | A2 | GND | A2 |
| −48V | A3 | −48V | A3 |
| −48V | A4 | −48V | A4 |

| ITEM | PART NUMBER | DESCRIPTION | QTY |
|---|---|---|---|
| 2 | 10066622-001LF | CABLE KIT CONNECTOR | 2 |
| 1 | 10069627-001 | POWER CABLE 2 COND.18 AWG | AR |

| ltr | ecn no | dr | date |
|---|---|---|---|
| A | M06-0293 | MHT | 6/07/06 |
| B | M06-0342 | AGS | 9/1/06 |
| C | M06-0386 | AGS | 10/3/06 |

mat'l. code | surface ISO 1302 | tolerance ISO 406 ISO 1101 | projection | product family: CABLE ASSEMBLY

tolerances unless otherwise specified: angles | linear: SEE TABLE | MM | scale NTS

| | | |
|---|---|---|
| dr | M.HERNANDEZ | 5/07/06 |
| engr | J.DUARTE | 5/07/06 |
| chr | J.DUARTE | 5/07/06 |
| appd | J.DUARTE | 5/07/06 |

title: POWER CABLE ASSEMBLY DUAL CONN. ERICSSON

dwg no 10070044 | sheet 1 of 1 | size A3

type: Product Customer Drawing

sheet index | revision C | sheet 1

form: A3

FCIconnect.com
Copyright FCI

PDM: Rev:C STATUS:Released Printed: Jan 19, 2011