

De las tabeli tehnicele sunt
 pentru detalii
 referitoare la
 dimensiuni si
 materiale



Part Name	QTY	Part No.	Part No.	Part No.
(1)	6	4100-3193	4101-1416	4102
(2)	30	4100-0152	4101-1417	4103
(3)	18	4100-0112	4101-1418	4104
(4)	30	4100-0111	4101-1419	4105
(5)	30	4100-0110	4101-1420	4106
(6)	30	4100-0109	4101-1421	4107
(7)	30	4100-0108	4101-1422	4108
(8)	30	4100-0107	4101-1423	4109
(9)	30	4100-0106	4101-1424	4110
(10)	30	4100-0105	4101-1425	4111
(11)	30	4100-0104	4101-1426	4112
(12)	30	4100-0103	4101-1427	4113
(13)	30	4100-0102	4101-1428	4114
(14)	30	4100-0101	4101-1429	4115
(15)	30	4100-0100	4101-1430	4116

Dimensiunile sunt in milimetri
 si sunt valabile pentru toate
 dimensiunile de fabricatie

Dimensiunile liberate sunt
 marcate cu *
 Dimensiunile liberate sunt
 marcate cu *

LASERMARKING SE RITN: 4100-4648
 LASERMARKING SEE DIMS: 4100-4648

Part No.	Part Name	QTY	Part No.
4101-1416	4101-1417 - 2x 4100-0731A	010712	FRMA




* 4100-3693, 4100-0152, 4100-0116, 4101-0014, D
 PACKS SEPARAT I PLASTICASE 4100-0479 DEH LAGGS I FORPACKNING
 PACED SEPARATY I N PLASTIC GAGS 4100-0479 AND SUPPLED IN BOX

- 4100-0479
- 4100-0016
- 4100-0522
- 4100-3693
- 4101-0014(D)

FIBRESPANNING / PRELOAD : 180±20 N
 KRIMP-HÖH/D/CRIMP HEIGHT 18-20 166±0.05
 22-26 154±0.05

152-002



Material	Quantity	Part No.	Part No.	Part No.
4100-0479	1	4100-0016	4100-0522	4100-3693
4101-0014(D)	1	4100-0152	4100-0112	4100-3964

Part No.	Part Name	QTY	Part No.
4101-1417	4101-1416 - 2x 4100-0731A	010712	FRMA

Part No.	Part Name	QTY	Part No.
4100-0479	4100-0016	4100-0522	4100-3693
4101-0014(D)	4100-0152	4100-0112	4100-3964