



FIG. 6 -K OPTION (USE K-DOT-.295-.406-.005) (SEAM-20-01-X-04-X-RA-K SHOWN)

CRITICAL DIMENSION INSPECTION INSTRUCTION TABLE					
ASSEMBLY	START-UP INSPECTION	IN-PROCESS INSPECTION			
OPERATION	INSPECT CODE A	INSPECT CODE B			
		C1, C2, C3, C4, C5, C7, C9,			
FILL WAFERS		C11, C12, C14, C15, C16,			
		C17, C18			
FILL WELD TABS		C6, C8, C10, C13			
FILL GUIDE POSTS		C19,C20			
FINISHED ASSEMBLY		C1, C2, C3, C4, C5, C7, C9, C11, C12, C14, C15, C16, C17, C18, C19			




TABLE 4					
STYLE	No. OF POS PER ROW	"J"			
	-20	0.74	[18.7]		
WITH -GP	-30	1.24	[31.4]		
OPTION	-40	1.74	[44.1]		
	-50	2.24	[56.8]		
	-20	0.57	[14.5]		
WITHOUT	-30	1.07	[27.2]		
-GP OPTION	-40	1.57	[39.9]		
	-50	2.07	[52.6]		

TABLE 5					
No. OF	"K"				
ROWS	ĸ				
-04	0.317	[8.04]			
-06	0.417	[10.58]			
-08	0.517	[13.12]			
-10	0.617	[15.66]			

