

02/10/99

Errata: CDB4340/41 Rev.A Evaluation Board Correction

(Reference CDB4340/41 Evaluation Board Data Sheet revision DS297DB1 OCT '98 and the CDB4340/41 evaluation board revision A.0)

Headers 15 and 17 and Test Points 6 and 8 are mislabeled. The correct labeling is as follows:

HDR15	DIF1/SCL/CCLK
HDR17	DEM0/AD0/CS
(Test Point) 6	DIF1/SCL/CCLK-A
(Test Point) 8	DEM0/AD0/CS-A

If there are any questions concerning this information,
Please contact Application Engineering at 512-445-7222
