



Description
SMA 50 Ohm Cable Jack -
Flange Mount Clamp Straight



Ordering Data
SMA 50 Ohm Cable Jack - Flange Mount Clamp Straight

Part Number	Cable RG-/U	Dimension						Finish	Mtg. Plate	Assembly Instructions
		A		B		C				
		mm	in.	mm	in.	mm	in.			
39JF101-1	174	20.64	0.813	7.94	0.313	7.94	0.313	Gold	5A	AI-61
39JF101-2	122	20.64	0.813	7.94	0.313	7.94	0.313	Gold	5A	AI-61
39JF101-3	58	20.64	0.813	7.94	0.313	7.94	0.313	Gold	5A	AI-61


Description
SMA 50 Ohm Cable Jack -
Flange Mount Solder Straight



Ordering Data
SMA 50 Ohm Cable Jack - Flange Mount Solder Straight

Part Number	Cable RG-/U	Dimension				Finish	Mtg. Plate	Assembly Instructions
		A		B				
		mm	in.	mm	in.			
39JF100-1	0.141 S.R.	14.29	0.563	9.53	0.375	Gold	5A	AI-318
39JF106-1	0.085 S.R.	12.70	0.500	9.53	0.375	Gold	6A	AI-318

Description
SMA 50 Ohm Cable Jack - Long Crimp Straight



Ordering Data
SMA 50 Ohm Cable Jack - Long Crimp Straight

Part Number	Cable RG-/U	Crimp Tool Hex		Dimension				Finish	Assembly Instructions
				A		B			
		mm	in.	mm	in.	mm	in.		
39J109-1	174, 316	3.25	0.128	36.51	1.438	26.99	1.063	Gold	AI-317