


MECHANICAL DRAWING :



1. All dimensions in Inch (mm)

Tolerance: $X.XX \pm 0.02$ ($X.X \pm 0.5$)
 $X.XXX \pm 0.01$ ($X.XX \pm 0.25$)

2. Pin pitch tolerance ± 0.01 (0.25)
 3. Pin dimension tolerance ± 0.004 (0.1)

PIN CONNECTION		
PIN	SINGLE	DUAL
1	+ INPUT	+ INPUT
2	- INPUT	- INPUT
3	CTRL	CTRL
4	+OUTPUT	+OUTPUT
5	TRIM	COMMON
6	-OUTPUT	-OUTPUT

EXTERNAL OUTPUT TRIMMING	
Output can be externally trimmed by using the method shown below.	
TRIM UP	TRIM DOWN
6 ○ ————— R _U ————— 5 ○	5 ○ ————— R _D ————— 4 ○

PRODUCT STANDARD TABLE	
Option	Suffix
Negative logic remote ON/OFF(Standard)	
Positive logic remote ON/OFF	-A
Without CTRL pin	-B
Negative logic remote ON/OFF without TRIM pin	-C
Without CTRL &TRIM pin	-D
Positive logic remote ON/OFF without TRIM pin	-E